ECS Configuration Change Request					Page 1 of	Pag	ge(s)
1. Originator	2. Log Date:	3. CCR #:		4. Rev:	5. Tel:	6. Rm #:	7. Dept.
Henry Baez	12/6/02	02-1062		-	301-925-1025	2101D	Sys Eng
8. CCR Title: Relase AIX 4.3.3 Maintenance Release 10 and fixes for firewalls in SMC and DAACs.							
9. Originator Signature/Date			10. Class		11. Type:	12. Need Date: 12-10-2002	
/s/ Henry Baez 11/18/02			II C		CCR		
13. Office Manager Signature/Date			14. Category of		(III : DI 1 07)		
/s/ James R. Mather 11/18/02				Initial ECS Baseline Doc. Routir			
3 1 1 1 1 1 1 1 1 1 1				7. Schedule 18. CI(s) Affected: mpact:			
19. Release Affected by this Change: 20. Date due				o Customer: 21. Estimated Cost:			
6A					None - Under 100K		
22. Source Reference: NCR (attach) Action Item Tech Ref. GSFC Other:							
23. Problem: (use additional Sheets if necessary) ECS firewalls are running OS AIX 4.3.3. IBM has release AIX 4.3.3 Maintenance Release 10 and fixes to correct some security and non-security problems. We have tested Maintenance Release 10 and fixes in VATC and PVC for several weeks with no problems. This is to release AIX 4.3.3 Maintenance Release 10 and fixes for loading on firewalls deployed at SMC and DAACs.							
24. Proposed Solution: (use additional sheets if necessary) Install Maintenance Release 10 and fixes on SMC and DAACs firewalls. Security levels need to be kept up to date to provide maximum protection for DAAC and SMC. Maintenance Release 10 comes on a CR-ROM. The four filesets are in a tar file call AIX4.3.3 ML10fixes.tar. Checksum: 3279087268 Blocksisze: 21135360							
25. Alternate Solution: (use additional sheets if necessary) None.							
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) For all sites there is risk that there might be attacks against a DAAC and production flows are severely impacted. The AIX 4.3.3 Maintenance Release 10 is also need if DVD drives are to be used on the firewall.							
27. Justification for Emergency (If Block 15 is "Emergency"):							
28. Site(s) Affected: ☐EDF ☐PVC ☐VATC ☐EDC ☐ GSFC ☐LaRC ☐NSIDC ☐SMC ☐AK ☐JPL ☐EOC ☐ IDG Test Cell ☐Other							
29. Board Comments:				30. V	Vork Assigned To	o: 31. CCR (Closed Date:
32. EDF/SCDV CCB Chair (Sign/Date): Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS							
33. M&O CCB Chair (Sign/D /s/ G. G. Gavigan 12/10/02	ate): Disp	position: App	proved	App/Co	m. Disapproved	Withdraw Fwo	J/ESDIS ERB
34. ECS CCB Chair (Sign/Da	ite): Disp	osition: App	roved	App/Com	n. Disapproved	Withdraw Fwo	J/ESDIS ERB

CM01JA00 Revised 8/2/02 ECS/EDF/SCDV/M&O

Fwd/ESDIS

ADDITIONAL SHEET

CCR #: 02-1062 Rev: - Originator: Henry Baez

Telephone: 301-925-1025 **Office:** 2101D

Title of Change: Relase AIX 4.3.3 Maintenance Release 10 and fixes for firewalls in SMC and DAACs.

The following documents are Impacted:

```
910-TDA-005 Site-Host Map Report
910-TDA-003 COTS S/W Version B/L Report
910-TDA-023 Critical COTS Software List
920-TDE-002 EDC Hardware-Sotware Map
920-TDL-002 LARC Hardware-Sotware Map
920-TDN-002 SMC Hardware-Sotware Map
920-TDP-002 PVC Hardware-Sotware Map
920-TDV-002 VATC Hardware-Sotware Map
```

Redline for 910-TDA-005, 910-TDA-003, and 910-TDA-023 are attach. For all Hardware-Software Map (920-TDx-002) the following information needs to be added.

Add the following hosts to the respective TDx:

e0fwi09 g0fwi09 l0fwi09 n0fwi09 m0fwi09 p0fwi09 t1fwi09

The function of these host should be "Firewall Server"

The software baseline for all the host above should be:

AIX 4.3.3 ml10
PORTUS 4.0
eBorder Enterprise 3.5 11/01
named 8.3.2-REL 7/02

CM01AJA00 Revised 8/2/02 ECS